


FIG. 1



F I G . 2




FIG. 3






FIG. 4




F I G . 5

$L^* = 90$




F I G . 6

$L^*=85$



F I G . 7


$L^* = 80$




000021 6/6/60

F I G . 8


$L^*=75$



$$L^* = 70$$



F I G . 10

$L^* = 65$



F I G . 11


$L^* = 60$



000021 000000

F I G . 12


$L^* = 55$



009021 6/6/8/60


F I G . 13

$L^* = 50$



F I G . 14


$L^* = 45$



003021" 6/6T6.60

F I G . 15


$L^* = 40$



000001" E26TE450

F I G . 16


$L^* = 35$



008027 " 6/67E/60

F I G . 17


$L^* = 30$



000021 6/6/60

F I G . 18


$L^* = 25$



003027 2 25 18 60


F I G . 19

$L^* = 20$



F I G . 20


$L^* = 15$



003021" 5/5T6/60


F I G . 21

$L^*=10$




F I G . 22

$L^* = 5$



F I G . 23A



F I G . 23B

R	G	R	G
G	R	G	R
B	G	B	G
G	B	G	B
R	G	R	G
G	R	G	R

F I G . 23C

Ye	Cy	Ye	Cy
Mg	G	Mg	G
Cy	Ye	Cy	Ye
Mg	G	Mg	G
Ye	Cy	Ye	Cy
Mg	G	Mg	G
Cy	Ye	Cy	Ye
Mg	G	Mg	G

F I G . 23D

	R	G	B	
G	B	R	G	
	R	G	B	
G	B	R	G	
	R	G	B	